

7.5 Parts, support with ball spindle drive

Qty.	Designation	Part number
1	Ball spindle drive 40x5	G60-20C660
1	Deep grooved ball-bearing	∅ 25/47x12 6005-2RS
1	Axial/radial bearing	ZARF 2575 TN
2	Toothed pully with taper lock socket	∅16 ^{H7} PL34-8M-20
1	Toothed belt	z=70 HDT 560-8M-20
1	Planetary gear	G60-20D710-P321-SPD-0100-ME
1	Servomotor with brake M ₀ =3,2 Nm n=3000 ^{min-1}	DSG 45 L-35-R-S
1	Small dial gauge	KM45SWA
1	Guard	G60-20B367
1	Guard	G60-20B700
1	Protective guide	G60-20C369
2	Pull string	7,5x1x155
1	Bellow	G60-20B667
1	Incremental length measurement system	MSA 670.63-P ML = 370 mm
3	Limit switch	M8x1 PNP- closer with reference
1	Worm gear	G60-20E375
1	Worm	G60-20E376
1	Cam roller 19x11/M8	GC19EE

7.5 Parts list, grinding motor GD30

Qty.	Designation	Remarks
1	O-ring 270x2	
1	O-ring 80x2,5	
1	Felt ring 100x24x10	Fi 22
1	Fan impeller	V 180R
1	O-ring 90x3	
1	Simmer ring	BA 105x130x12
1	Gasket	V-120A
2	Spindle bearing	A7217 ET P5 DUM
1	Deep groove ball bearing	6213 RS
2	Coils for mounting flange	
1	O-ring OR 30x3	
1	O-ring 300-3	
1	Pressure spring 6.4x0.7x41	
1	Slip ring element	G60-21E21
2	Brush holder, complete	A15x1/AS